

CARR - 689

606 UNIONTOWN ROAD

late 19th century

Westminster vicinity

private

606 Uniontown Road appears to have been built between 1862 and 1877 (from Carroll County map references). The structure is a bank house with a full-story basement on its east and south facades. The asymmetrical facade indicates the possibility that this is a log structure; the exterior is covered in German siding. Although there are modern additions on the south and east facades, the house still retains the basic proportion and appearance of a representative mid-to-late nineteenth century house in this region.



## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

## FIELD SHEET--HISTORIC RESOURCES SURVEY

417

SURVEY NUMBER:

CARR-689

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

New Windsor

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

residence

ORIGINAL USE:

residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ( )

Good (X)

Fair ( )

Poor ( )

THEME:

STYLE:

DATE BUILT:

COUNTY:

CARROLL

TOWN:

Westminster vic.

LOCATION:

606 Unimtown Road

TAX MAP 38 Block 23 P-328

COMMON NAME:

FUNCTIONAL TYPE:

residence

OWNER:

Roger D. Warehime

ADDRESS:

ACCESSIBILITY TO PUBLIC:

Yes ( )

No (X)

Restricted ( )

LEVEL OF SIGNIFICANCE:

Local ( )

State ( )

National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )

2. Wall Structure ?

A. Wood: Log (X) Post and Beam (X) Balloon ( )

B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )

C. Iron ( ) D. Steel ( ) E. Other

3. Wall Covering: Weatherboard ( ) German Siding (X) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:

4. Roof Structure

A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )

B. Other:

5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:

6. Engineering Structure:

7. Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells ( ) Wings (X) Other:Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories:

2

Number of Bays:

3x2

Approximate Dimensions:

Entrance Location: side of enclosed porch

THREAT TO STRUCTURE:

No Threat ( ) Zoning ( ) Roads ( )

Development ( ) Deterioration ( )

Alteration ( ) Other:

LOCAL ATTITUDES:

Positive ( ) Negative ( )

Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

enclosed modern front porch on concrete block foundation  
 asymmetrical facade give the appearance of a log structure  
 modern 1 story wing on east gable end

## RELATED STRUCTURES: (Describe)

Frame shed

## STATEMENT OF SIGNIFICANCE:

From maps - appears to have been built between 1862 and 1877

## REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas: Margaret Royer (one of 3 Royer properties)

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
 Moderately Built Up ( ) Densely-Built Up ( )  
 Residential ( ) Commercial ( )  
 Agricultural ( ) Industrial ( )  
 Roadside Strip Development ( )  
 Other:

## RECORDED BY:

Jae Getty

## ORGANIZATION:

## DATE RECORDED:

8/83

*Scale 2 Inches to the Mile*

CARR-689



U.S.G.S. MAP  
NEW WINDSOR, MD.  
1:24000 SCALE





1. CARR-689 606 UNIONTOWN ROAD
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. South and east elevation  
(camera facing northwest)
7. 1/1